

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

#### Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0410002
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, March 16, 2010
Start Date/Time:	3/16/2010 11:00:00 AM
End Date/Time:	3/16/2010 4:00:00 PM
Last Inspection:	Wednesday, February 03, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, Temp. 45 Deg. F.</u> InspectionID Report Number: <u>2300</u>

**Types of Operations** 

Accepted by: jhelfric

3/22/2010

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### Current Acreages

25,292.43	<b>Total Permitted</b>
48.43	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

#### Mineral Ownership

✓ Federal
✓ Underground

✓ State
□ Surface

□ County
□ Loadout

□ Fee
□ Processing

□ Other
□ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

LeLand Roberts SUFCO was present during the inspection.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utah!

Tuesday, March 16, 2010

**Date** 

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, March 16, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		<b>V</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.					
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, March 16, 2010

Page 3 of 3

### 2. Signs and Markers

The mine identification signs located at the point of public access at the refuse pile and mine site contained the required information.

# 7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards were observed.

## 8. Noncoal Waste

The mine site was free of noncoal waste items. Prper storage of noncoal waste items is being utilitized.